


REPORT

DUPLICATE

TRUESDAIL LABORATORIES, INC.

HEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING14201 FRANKLIN AVENUE
TUSTIN, CALIFORNIA 92680
AREA CODE 714 • 730-6239
AREA CODE 213 • 225-1564
CABLE: TRU ELAB 9CLIENT Douglas Aircraft Company
Internal Mail Code 211-40
3855 Lakewood Blvd.
Long Beach, CA 90846
SAMPLE Attention: Robert M. TomkoDATE December 20, 1988
RECEIVED
LABORATORY NO. December 15, 1988
31561

Monthly Storm Drain Inspection (December, 1988)


INVESTIGATION P.O. #T & M 23465 C

Analysis as requested by the CRWQCB for NPDES Permit No.'s:
CA0001486 & CA0001414

RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on December 15, 1988, at the Douglas, Long Beach (003) and Torrance facilities. The discharge was tested for flow rate, pH and temperature. The results are as follows:

<u>Sample I.D.</u>	<u>Date</u>	<u>Time</u>	<u>Flow-gpd</u>	<u>Temp</u>	<u>Ph</u>
Long Beach (003)	12-15-88	3:10	184,720	58	6.8
Torrance	12-15-88	1:30	300	90	6.5

Respectfully submitted,
TRUESDAIL LABORATORIES, INC.
Luis Perez, Supervisor
Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.